

TIMKEN®

THE TIMKEN COMPANY

GENERAL OFFICES
CANTON, OHIO, U.S.A. 44706-2798
TELEPHONE: (216) 438-3000



March 17, 1989

Mr. Kelvin F. Rogers
Environmental Scientist
Division of Water Pollution Control
Ohio Environmental Protection Agency
2110 East Aurora Road
Twinsburg, OH 44087

Dear Mr. Rogers:

In regard to your letter and the overage on January 30, 1989 at Outfall 007 (9.3 pH), there is no apparent reason for the overage; however, we are investigating. Recently, due to the warmer weather, we have begun to restone the various laydown areas, which has, in the past, caused overages at some of the outfalls due to carryoff of lime from the limestone.

If you have any questions regarding this, please contact me.

Sincerely,

A handwritten signature in cursive script, reading "William E. Lacure".

William E. Lacure
Environmental Control
Coordinator

rjm/B:340.wel

RECEIVED

MAR 21 1989

OHIO EPA-N.E.D.O.